

Annexure- D

BUILDING SAFETY CERTIFICATE

No. EG/ 26-27/08.....

Dated: 25-08-2026.....

It is certified that the existing building .DDM PUBLIC SCHOOL. (name of the building or premises) at .
BEHIND INDIRA STADIUM, KORBA (C.G.)

..... (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	2 FLOORS	1 FLOOR				

The building is owned/occupied by.DDM PUBLIC SCHOOL. (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **NIDHI AGRAWAL, STRUCTURAL ENGINEER,** (Name of Department/ Govt.) on.23-08-2026. (date of inspection) in the presence of .**Mr. ASHOK KUMAR DOGRA, PRICIPAL,** DDM SCHOOL. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from.1998. for a period of.28. years in accordance with rule and subject to compliance of the specific conditions as appended.

1. SCHOOL BUILDING IS SUFFICIENT STRONG ENOUGH TO TAKE ALL TYPE OF LOAD.
2. SCHOOL IS 100 MT AWAY FROM MAIN RAOD, SO THERE IS NO HEAVY TRAFFIC.

Issued on .25-08-2026. at .KORBA (C.G.). by


* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.


Signature with Seal : 

Name : _ENGR. NIDHI AGRAWAL_

Designation : M. TECH (STRUCTURAL ENGG.)_







Name & Address of Department/ Office

Nidhi's Road, KORBA (C.G.)

Mobile: 9827172118